CONDITION REPORT - INTERNAL COMBUSTION

Manufacturer	Model	Year	Serial Number	Corrected
HYSTER COMPANY	E40XN	2017	A269N03359R	A269N03359R
Mast	3 Stage FFL (Triplex)		Hours	13790
Mast Height Lowered	82		Fuel	Electric
Mast Height Raised	187		Attachment	Carton Clamp
Hydraulic Control Valve	4-Function		Directional Control	Monotrol
Capacity	4000		Tires	Cushion
Mast Condition			Engine	
Mast Comments			Engine Inspected Condition	
Lift Cylinder Condition			Engine Inspected Comments	
Lift Cylinder Comments			Radiator Condition	
Tilt Cylinder Condition			Radiator Comments	
Tilt Cylinder Comments			Transmission/MDU Condition	
Carriage Condition			Transmission/MDU Comments	
Carriage Comments			Transmission/MDO Comments	
Load Backrest Condition			Steering Pump Condition	
Load Backrest Comments			Steering Pump Comments	
Forks Condition			Hydraulic Pump Condition	
Forks Comments			Hydraulic Pump Comments	
TORS COMMENTS			Hydraulic Motor Condition	
Overhead Guard Condition			Hydraulic Motor Comments	
Overhead Guard Comments			Control System Condition	
Overnead Guard Comments				
Seat Condition	Domonod		Control System Comments	
	Damaged		Differential Condition	
Seat Comments	ripped		Differential Condition	
O I A O I'd	E. S.		Differential Comments	
General Appearance Condition	Fair		Drive Tires % Remaining	
General Appearance Comments	Impact damage		Drive Tires Condition	
			Steer Tires % Remaining	100%
General Comments			Steer Tires Condition	
battery dirty, seat ripped, seatbelt damaged	ed, bolt missing in rear cover, clamp bearing	s worn, steer cylinder seeping	Steer Axle Condition	Leaks
fluid, freelift chains worn out, brake fluid dirty			Steer Axle Comments	
			Brakes Condition	
			Brakes Comments	
			Electrical Condition	
			Electrical Comments	

Inspector Company Name	Eastern Lift Truck	Inspection Date	2/6/2023 11:18:32 AM	
Inspector Name	jpellini			























