## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number	Corrected
HYSTER COMPANY	E50XN	2017	A268N20772R	A268N20772R
Mast	3 Stage FFL (Triplex)		Hours	13195
Mast Height Lowered	83		Voltage	36 Volt
Mast Height Raised	189		Attachment	Carton Clamp
Hydraulic Control Valve	4-Function		Directional Control	Monotrol
Capacity	5000		Tires	Cushion
Mast Condition			Steering Pump Condition	
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition			Control System Condition	
Carriage Comments			Control System Comments	
Load Backrest Condition			Control System Comments	
Load Backrest Condition  Load Backrest Comments			Drive Motor Condition	
Forks Condition			Drive Motor Comments	
Forks Comments			Differential Condition	
0 - 1 - 1 0 - 1 0 - 186 -			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	
Overhead Guard Comments			Drive Tires Condition	
			Steer Tires % Remaining	100%
Seat Condition	Damaged		Steer Tires Condition	
Seat Comments	coming apart		Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition	Excellent		Brakes Condition	
General Appearance Comments	Impact damage		Brakes Comments	
General Comments			Battery Present	Yes
trunion bushings have play, front blue ligh	t loose, clamp bushings worn, seat coming	apart at bottom, freelift chains	Charger Present	Yes
worn out, play in fourth function linkage				
			Electrical Condition	
			Electrical Comments	

Inspector Company Name	Eastern Lift Truck	Inspection Date	2/8/2023 9:28:03 AM	
Inspector Name	jpellini			























