## **CONDITION REPORT - ELECTRIC**

Manufacturer	Model	Year	Serial Number	
YALE	OS030BF	2019	E826N05042T	
Mast			Hours	6269
Mast Height Lowered	10		Voltage	24 Volt
Mast Height Raised	25		Attachment	
Hydraulic Control Valve			Directional Control	
Capacity	2000		Tires	Non-Marking
Mast Condition			Steering Pump Condition	
Mast Comments			Steering Pump Comments	
Lift Cylinder Condition			Hydraulic Pump Condition	
Lift Cylinder Comments			Hydraulic Pump Comments	
Tilt Cylinder Condition			Hydraulic Motor Condition	
Tilt Cylinder Comments			Hydraulic Motor Comments	
Carriage Condition			Control System Condition	
Carriage Comments			Control System Comments	
Load Backrest Condition				
Load Backrest Comments			Drive Motor Condition	
Forks Condition			Drive Motor Comments	
Forks Comments			Differential Condition	
			Differential Comments	
Overhead Guard Condition			Drive Tires % Remaining	80
Overhead Guard Comments			Drive Tires Condition	
			Steer Tires % Remaining	
Seat Condition			Steer Tires Condition	Not-Selected
Seat Comments			Steer Axle Condition	
			Steer Axle Comments	
General Appearance Condition	Good		Brakes Condition	
General Appearance Comments			Brakes Comments	
General Comments			Battery Present	Yes
	and demonstrated the second	and date a control of	Charger Present	Yes
operator lights not working platform gate a missing	rms damaged drive unit cover hardware missi	ng drive unit doors hardware	Charger Fresent	165
			Electrical Condition	
			Electrical Comments	
			Liectrical Comments	

Inspector Company Name	eastern lift truck	Inspection Date	3/27/2023 9:30:05 PM	
Inspector Name	Tjcolvin			

























